MODEL 163.113 /128 /136 /154 /157 /172 /174 /175
Door sill molding in cargo space

1 Caps
2 Door sill molding



P68.30-2393-11

	Remove/install		
1	Remove cover caps (1)	Do not scratch door sill molding.	
2	Remove screws below caps		
3	Remove door sill molding (2)	**Installation:** Ensure that sealing rubber is positioned correctly.	
4.1	Disconnect connector from electronic compass	Only as of 01.09.00 and with code (245), trip computer.	
5	Install in the reverse order		

Copyright DaimlerChrysler AG 28.05.2006 CD-Ausgabe G/10/04 . This WIS print-out will not be recorded by Modification services.